







5 Gap 41 Ø 20 41 Ø 20 37 3.5 3.5 58 65 65 58 3.5 3.5 Ø 20 Ø 20 CUTTING THE GLASS AT THE TOP AND BOTTOM (all dimensions are in mm)

PREPARATION OF THE GLASS